

Chief Surveyors

Received from Chief Surveyors

EL'S NAME *Stat 5-5 LARGS BAY*

Report

GL

No.

*41612***For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey

When due

❖ 100-A-1. (Steel) Shelter Deck with foreboard
 2 Dks (Steel) v Shelter Dk (Steel w/s) 3rd Dk (Steel) in forward holds
 All DB 457' 2259t, MTZ 1017t Tanks between tunnels 51' 197t FPT 174t, APT 143t
 FK, 9 BH to Shelter Dk, pt Low, hly 40 A v P, BZ 15' F76' on Shelter Deck

TH
 29.12.21

Surveyors should be requested to state the length and capacity of the water tanks between the tunnels; they should also be requested to state whether figure given for the capacity of the deep tank is oil capacity and if so to state water capacity if the tank is to be used for water ballast.

S. L. H.
 4.1.22

Lloyd's Register
 Foundation