

No 1868

2 cylinder covers, 2 cylinder liners, 2 pistons, 2 connecting rods, 2 bottom end bearings, 3 top end bearings, 3 main bearings.

Manufacturer.

Lloyd's Register
Foundation

003409-003416-0061

4^c 1868

Dates of Survey while building { During progress of work in shops - - }
During erection on board vessel - - }
Total No. of visits 5

Dates of Examination of principal parts—Cylinders Port 9.12.47 S. 17.11.47 P 9.12.47 S 17.11.47 P. 9.12.47 S 17.11.47 Covers S. 17.11.47 Pistons S 17.11.47 Piston rods. -

Connecting rods Port 9.12.47 Stbd. 17.11.47 Crank and Flywheel shafts P. 9.12.47 S. 17.11.47 Intermediate shafts. -

Crank shaft { Material - Tensile strength -
Elongation - Identification Marks -

Flywheel shaft, Material - Identification Marks -

Is this machinery duplicate of a previous case - Identification Marks -

Identification marks on Air Receivers. -

Is this machinery duplicate of a previous case. - If so, state name of vessel. -

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.) These auxiliary engines were originally built under the special supervision of the Surveyors to the American Bureau of Shipping and classed with that Society but have now been surveyed by me for Classification with this Society.

The condition and standard of workmanship, as now seen, is considered to be good and satisfactory

Please see Rpt. 4b regarding opinion as to class, &c.


The amount of Fee ... £ : -- : { When applied for - 19
Travelling Expenses (if any) £ : -- : { When received - 19

Committee's Minute

Assigned

see JE Rpt.

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation