

Received from Chief Ship Surveyor 16 OCT 1962

SHIP'S NAME "HUSEYIN KAPTAN" REPORT Ist. No. 5232

B

Outstanding Conditions of Class:

SUBJECT to shell plate No.2 in 5th & 6th strakes below sheerstrake (p.s.f) being specially examined and dealt with as found necessary by the next drydocking and to a bower anchor and 30 fathoms of chain cable being supplied at the earliest opportunity.

S.R.L. Appendix. (As before ~~mentioned~~)

Nature of Present Survey: (Afloat ~~and in drydock~~)

Equipment - a bower anchor and 30 fathoms of c.c. supplied, but as this was salvaged equipment certificates were not available.

Recommendation:

SUBJECT to shell plate No.2 in 5th & 6th strakes below sheerstrake (p.s.f) being examined and dealt with as necessary by the next drydocking and to the weight of the bower anchor (supplied Ist.9,62) being ascertained at the earliest opportunity.

As Now. Subject

Amended.

IN S.R.L. APPENDIX.

Indented shell plating (p & s).



© 2021

P.T.O.

Lloyd's Register
Foundation

IT IS FURTHER SUBMITTED the Surveyors be
advised that the weight of the anchor has to be ascertained
and particulars forwarded to this Office, and in future
similar cases he should arrange for the anchor to be
weighed to satisfy himself that the weight approximates
the Rule weight.

W.T.
9/10/62

See letter
22/10/62



© 2021

Lloyd's Register
Foundation