

WRECK SECTION

18168

Rpt. 9

Date of writing report 10 Feb. 1961

Survey held at Melbourne

Received London

No.

Port

No.

No. of visits Two

First date 24-1-61

Last date 1-2-61

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 78227 Name S.S. "RUNIC" Gross tons 13587 Date of build 3-1950

Owners Shaw Savill and Albion Co. Ltd. Managers Port of Registry Southhampton

Engines made 3-1950 By Harland & Wolff Ltd. Type 6 turb. SR geared to 2 SC shafts

No. of Main Engines 2 No. of Screws 2

No. of Main Boilers 2 W.P. 490

No. of Aux./Donkey Boilers - W.P. -

Surveyed Afloat or in Dry Dock Afloat

Nature of Survey Machy. Damage

Was Damage Report issued? Yes Int. Cert.? Yes

Last Report (For Head Office only)

11729 nwc

Records of Survey & Special Notations as per Register Book

Hull	Machinery
+ 100 A1	+ LMC
SS 8-58	Eng. 2-58
Docking 5-60	M.B.S. 5-59
	TS CL P&S 7-58
	SPS 2-58

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs" At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers Wear Down of Stern Bushes Oil Glands Sea Connections

Fastenings Has Screwshaft/Tubeshaft been drawn? Date of Examination Has Shaft been changed?

Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?

MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD

1 Cyls., Covers, Pistons & Rods

2 Valves & Gears

3 Connecting Rods, Top Ends & Guides { Side Centre

4 Crankpins & Bearings { Side Centre

5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES

Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS

This vessel's machinery, so far as seen, is eligible in my opinion to remain as classed in the Register Book without fresh record of survey.


Date of Committee

THURSDAY 9 MAR 1961

Decision

As now subject

A. L. Simpson
Engineer Surveyor to Lloyd's Register of Shipping



Lloyd's Register Foundation

If certificate is required state where to be sent

Note Mel duty

Handwritten signature

32 Essential Independent Pumps (Identify by position)

33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls

34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?

35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)

38 Independent Air Compressors, Coolers & Safety Devices

39 Air Receivers & Safety devices—Main Auxiliary

41 Oil Fuel Tanks (Not forming part of hull structure)

42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?

44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

ELECTRICAL EQUIPMENT

PROPULSION	PORT	STARBOARD	AUXILIARY EQUIPMENT
a Generators			Generators & Governors
b Exciters			
c Air Coolers			m Motors
d Motors			
e Air Coolers			n Switchboard & Fittings
f Control Gear, Cables, etc.			o Circuit Breakers
g Insulation Resistance			p Cables
h Insulating Oil Test			q Insulation Resistance
i Overspeed Governors			r Steering Gear Generators and Motors
j Magnetic Couplings			s Navigation Light Indicators
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN AUXILIARY, DONKEY or PRESS

Superheaters

Safety Valves

Mountings, Doors & Fastenings

Safety Valves Adjusted to { Sat. Spt.

Boiler Securing Arrangements

Main Economisers Exhaust Gas Heated Economisers

Steam Heated Steam Generators Steam Generator Safety Valves Adjusted to

Were Oil Burning System & Remote Controls examined working in accordance with Rules? Forced Circulating Pumps

Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)

Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

At the request of the Owners Representative an examination now made of the port main boiler-air preheater (see Melbourne Damage Report Crtf. No. D 1561).

It was stated that the preheater caught fire whilst manoeuvring at Port Said on the 24-12-60 and the fire was extinguished by using sea water from the deck service line. It would appear that the fire was on the air side of the heater. The vessel proceeded to Melbourne by-passing the damaged preheater. Upon examination six sectors of the preheater found to be damaged and it was stated that repairs would be effected at New Zealand, this voyage. It is considered by the undersigned that the boiler is remaining efficient meanwhile.

LEAVE THIS SPACE BLANK

[Handwritten signature]

Survey fees £10 - 0 - 0

Damage fee See Damage Report

Expenses

Date when A/c. rendered 6-2-61



© 2021

Lloyd's Register Foundation