



been satisfactorily re-stalled. Generator examined under  
working conditions and found satisfactory  
First Entry Report No.      herewith attached (not yet received from Law. Ins)

REPAIRS: Boiler - local internal wastage reinforced with  
electric welding. Several stays renewed.

New Generator: The generator main cables as existing, were removed  
and replaced by new cables of suitable size for  
the new machine and a new C.O. Main Switch  
was fitted to the main switchboard, and a new  
ammeter of suitable size will be fitted as soon as  
delivering to the vessel is possible. The new equipment  
as now installed was tested and found satisfactory.

S. D. Mann



© 2020

Lloyd's Register  
Foundation

ON BEHA