

10 AUG 1956

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SHIP'S NAME "KYLOE"

JD. REPORT Nwc. No. 113523.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey PERIODICAL SPECIAL SURVEY (D) due 3, 56.  
( ship 26 years old ).

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch.

STRAKE.	AMIDSHIP.						FORWARD.						AFT.						REMARKS.
	Original Thick- ness	Thickness by drilling.		Diminution if any.		Original Thick- ness.	Thickness by drilling.		Diminution if any.		Original Thick- ness.	Thickness by drilling.		Diminution if any.					
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.				
DGESHEER	✓ 47	48	52	-	-	-	-	-	-	-	-	34	37	34	-	-			
		48	52	-	-	37	40	39	-	-	-	34	20*	35	14	-			
		62	52	6	16	42	47	50	-	-	-	42	45	50	-	-	* - renewed.		
		49	53	8	4	42	47	37	-	5	-	42	36	37	6	5			
		43	47	9	5	42	50	42	-	-	-	42	30	37	9	5			
		53	52	-	-	42	43	50	-	-	-	42	37	38	5	4			
		Cement				42	50	40	-	2	-	42	30	45	12	-			
		"				44	32	35	12	9	-	44	39	40	5	4			
		"				44	-	-	-	-	-	44	-	-	-	-			
		"				44	-	-	-	-	-	44	-	-	-	-			
		"				57	-	-	-	-	-	57	-	-	-	-			

Drillings at ends to be made in the vicinity of the peak bulkheads.

The class is subject to the raised deck between Nos. 3 & 4 being specially examined and dealt with as necessary by next survey.

ACTION is DEFERRED for examination in drydock after

The NEWCASTLE Surveyors report this ship placed in drydock damages from various causes, repairs effected to shell etc. (p&s).

The requirements of a Special Survey (D) have been complied repairs effected to shell and deck plating, etc. also in holds.

The thickness of shell plating has been ascertained by drilling with results as above, which are satisfactory.

The results of the drilling of the deck plating are also considered satisfactory.

003434-003443-0353 1/2 Cont/....



10 AUG 1956

Cont/..... "KYLOE"

Conditions of class dealt with.

Concurrently with the above, this ship has been converted to ~~the~~ carriage of oil fuel in accordance with approved plans, the Rules, and the arrangements decided upon locally.

IT IS SUBMITTED the ship is eligible to have record of docking 6,56 and notation of "ss.Shl. 6,56(Dr)" assigned, without special condition.

*Ly.*

6,56 Shl. } Without.  
ss. Shl. 6,56(Dr).

INSERT IN R.B.

O.F. 6,56.

M.T. O.F.

Side tanks in B.R. O.F.

DELETE FROM S.R.L.

Drydocking (grounding).

NOTED FOR  
POSTING  
Noted  
for  
Head

IT IS FURTHER SUBMITTED the surveyors be advised it is concluded that the drilling thickness furnish for the shell plating in D strake (p.s.a.) is not indicative of the general condition of the plating but only of a locally wasted spot.

*X 14/8*

*BM.  
26.7.56*



© 2020

Lloyd's Register  
Foundation

0353 2/2