

2 OCT 4E 1957

d by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....


S NAME.....SUNFLEET.....REPORT.....Hul.....No.....63413

MBS due 10.57, now held.

Docking. Screwshaft seen at Owners' request.
The liner found excessively worn at bearing and the screwshaft
now renewed.

IT IS SUBMITTED this vessel is eligible for the record
MBS 9.57, TSN (CL) 8.57.

25.9.57.



R

© 2021

Lloyd's Register
Foundation

003450-003457-0031