

See also endorsement dated 6.1.58.

23 JAN 1958

Received from Chief Ship Surveyor

NAME "TRIBEAM" REPORT Smk No. 814.

Condition of Class: Subject to set in shell plate
G.9 etc.(p.s.) being dealt with as necessary next
Special Survey.

Assignment of Class (B) (~~As before~~ or None)

Place of Present Survey: (~~Afloat and in dry dock~~)

Equipment - reported loss of 7 lengths of c.c.
and 1 bower anchor on account of chain cable fracturing
through whilst moored. 7 lengths of c.c. recovered
and refitted and efficient temporary arrangements effected
for joining chain cable. Spare bower anchor housed.

SUBJECT as above, and to a bower anchor
being supplied and to enlarged end links being
fitted to starboard chain cable as ^{considered} necessary
at the earliest opportunity.

As Now. Subject.

IT IS FURTHER SUBMITTED the Owners be advised
of the Condition of Class regarding equipment and be
requested to advise this Office what arrangements they
are making in this connection.