

4- OCT 1962

Ship's name

"ETTRICKBANK"

Port DRB. 9

No. 5138

Ship is subject to indented side shell plates ^{Last survey date 19.9.62} J.8, H.8, G.6 (p.s. from aft) indented bottom A.15 & 16, B.15 & 16, C.16 (s.s. from aft), upper deck plating (p.s), and forward bulkhead of deep tank (p.s) (fire damage) being specially examined and dealt with as necessary by the S.S., to permanent repairs to side shell plates H.9 & 10 (p.s. from aft) also to indented shell plates G.12 and H.13 (p.s) being specially examined, next drydocking. ACTION is DEFERRED for Special Survey by 7,62.

R.L. Appendix (~~XXXXXXXXXX~~ none)

Surveys due

SPECIAL SURVEY (D) due 7,61. Postponement until 7,62 approved 28.6.62 following a satisfactory G.E. Request for further postponement until 10,62 approved 3.7.62 following a further G.E.

Structure of present survey (afloat and ~~in drydock~~)

Equipment: Bower anchor and 3 lengths of chain cable removed.

Interim certificate in order

Yes/~~XXXXXXXX~~

Items outstanding if any for SS

ALL ITEMS.

Proposed to be completed by 10,62.

Commendation

SUBJECT as above and to a bower anchor and 3 lengths of chain cable being supplied at the earliest opportunity, but ACTION continue to be DEFERRED for Special Survey by 10,62.

SUBJECT.

NOTE

It would appear from this report that it is intended to sell the ship in the Far East for breaking up on discharge of cargo.



© 2020
 Lloyd's Register
 Foundation

25.10.62

On Regn 24/9