

Rpt. 8

TAIPEI

No. 61-8-26

27. FEB. 1962

Date of writing Report 9th Feb. 1962

When handed in at Local Office

Received London

First Date 24th Aug. 1961

Last Date 6th Sept. 1961

Survey held at Keelung & Kaohsiung

No. of Visits 4

REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

41571

on the Iron or Steel M.S.

"UNION RELIANCE"

Tons gross 7638

Year Month

When 1940

Built at Chester, Pa.

By Whom Sun S.B. & D.D. Co.

Owners China Union Lines Ltd.

Owners' address (If not already in R.B.)

Port of Registry Keelung

Managers

Date of last examn. in Drydock

Surveyed Afloat or in Drydock Afloat

Name of Dock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

10020

Port

Mo

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
100 A1 with freeboard	LMC
SS 2/57	CS 3/57
Dkg 4/61	ABS 5/61
	TSCL 4/60

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified - ft - in

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR NEW LIFE BOAT DECK & FOUNDATION

Conversion:

Two new life boat deck supports fitted on after well deck port & starboard side as shown in attached blue print, and found satisfactory on completion.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent? Now

Has Interim Certificate been issued? Yes

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This vessel, so far as now seen is efficient and eligible in my opinion, to remain as now classed without fresh record of docking survey.


Henry S.M. Tan
Acting Surveyor to Lloyd's Register of Shipping
Henry S.M. Tan

THURSDAY 22 MAR 1962

Date of Committee

Minute

Note - See Committee Minute dated 9.2.62



© 2020

Lloyd's Register Foundation

003479-003486-0014

See Annex
at 11/2/62
2.F.C
9/2/62

Note Taipei 2013

TABLE 1

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR NEW LIFE BOAT DECK SURVEY

Items	Now Examined		Tanks	Now Examined Internally	Now Tested
	YES	NO or NONE			
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock			F.P. Tank		
Rudder lifted			A.P. "		
Weather Decks, Superstructures and Casings			D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances					
Ventilator coamings, skylights, companionways and closing appliances			Fresh Water Tanks		
Holds			Deep Tanks		
'Tween Decks			Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces			Side Tanks		
After " "			Wing Tanks		
Engine Space			Other Tanks		
Boiler "			Cargo Tanks (Tankers)		
Under Engines and Boilers					
Tunnel and Well			Cofferdams		
Coal Bunkers			Pump Rooms		
Chain Locker					
Other Spaces					
			Have Tanks now Examined been Cleaned as Necessary?		
			Have Strums in Cargo Tanks (of Tankers) been removed?		
			Have Tanks been Retested as necessary after completion of any Repairs?		

Have the spaces now surveyed been cleared and cleaned as necessary?
 Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules?
 Have the bilges been cleaned out and examined? Has cement in bottom been examined?
 Has steelwork had rust removed and afterwards been recoated as necessary?
 Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork?
 Has a Load Line Survey been held? If so, state which
 Have the shell and deck plating been drilled as per Rule? If so, Report 8(Dr) to be attached
 Have any alterations to the approved scantlings and arrangements now been effected? If so, report details in body of Report.

NOTE: Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

TABLE 2

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found	
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes	
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes	
Decks	Hatches and closing appliances	Masts and Rigging examined and found	
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)	
Coamings and Casings	Companionways and Skylights	Chain Locker	
Beams and Fastenings	Shell Openings	EQUIPMENT	
Frames	Ash Shoots	Equipment Letter	
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition	
Longitudinals	Freeing ports	Cables (State if now ranged and examined)	
Transverses	Steering Gear (Main and Auxiliary) examined and found	" length mean diam. (on board)	
Floors	Windlass examined and found	" Rule Length Size	
Keelsons	Pumps " " "	Hawsers and Warps	
Stringers	W.T. Doors " " "	State if any Anchors or Chain Cable have now been supplied or retested, if so complete Report 8(Eq) and attach.	

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee \$ 90.00
 (75% to be credited to the Surveyor concerned)
 Special Damage or Repair Fee (if any)
 Travelling Expenses (if chargeable) 35.00
 Second Surveyor's Fee (if any)
 Date when A/c. Rendered
 Lloyd's Register Foundation