

COPY OF AIR LETTER

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

28th February, 1958.

GURACAO.

5296 - As recommended.

5303 "TENAGOHUS" As recommended. It is concluded that in the event of tubes becoming defective in the area of the welded handhole they can still be plugged, but I shall be glad to have your comments on this.

5272 "ROSA" As recommended. The class of this ship was subject to repairs to cracked and doubled shell plate at forward end of Engine Room (port side) being examined at the next drydocking, and dealt with if necessary, also to sheerstrake plate (port side) in way of No. 1 wing tank (doubled 1,57) being examined and dealt with as necessary and to shell plating in way of No. 3 port wing tank (leakage) being examined and dealt with as necessary at the next drydocking. I shall be glad to have your confirmation that these matters received attention at this time.



© 2020

Lloyd's Register
Foundation

003487-003494-0165