

Received from Chief Ship Surveyor..... 21 SEP 1962

SHIP'S NAME "HENRIK DANICA" REPORT Hav. No. 10439
 GB

Outstanding Conditions of Class: NONE

ACTION is DEFERRED for examination in dry dock
 after grounding.

S.R.L. Appendix. (As before ~~xxxxxxx~~)

Nature of Present Survey: (~~xxxxxxx~~ in dry dock)

Docking: Damage (grounding) involving bottom shell plating (p & s.f.)

Recommendation:

SUBMITTED record of 'DS 8,62' be assigned,
 subject to No.1 keel plate from forward
~~and bottom shell plates B.3 & 4~~
 (~~p.s. from fwd~~) being examined and dealt
 with as necessary next drydocking.

DS 8,62 Subject

IN S.R.L. APPENDIX.

Soft nose stem plate indented.

Shell plates in 'F' & 'G' strakes (p & s)

abreast No.1 hatchway indented.



© 2020

Lloyd's Register
 Foundation

P.T.O.

IT IS FURTHER SUBMITTED the Surveyors
be advised in view of the remarks in their report
concerning shell plates B.3 & 4 (p.s. from fwd) which they
have recommended be replaced, it is ~~concluded~~ that these
two plates ~~should have been made a condition of class.~~

*dealt with at this time since they are not
included in their recommendations to the Committee
but confirmation is desired*

*S.P.H.
11/9/62*

*See letter
dated 3/10/62*



© 2020

Lloyd's Register
Foundation