

003487-003494-0236

4E

subject to

P.F. Auxiliary Engine entablature and Nos. 5 and 6 bedplate cross girders (Metalocked 4.61) being examined by 3.63 (12 months limit).

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor... 21 SEP 1962

"S NAME" "HENRIK DANICA" REPORT HVR No. 10439.

Damage stated due to grounding.

Screwshaft examined.

IT IS SUBMITTED that this vessel is eligible for THE RECORD TS (OG) 8.62, subject as above.

NOTE.

The Surveyor should be informed it has been concluded the screwshaft was in fact magnaflux tested and skimmed up, also that the sternbush and oil gland were dealt with as recommended but please confirm.

© 2020

19.9.62.

Comp. 19.9.62. Register

see letter 3/10/62 1/1/62