

Translated copy of letter dated 30th November 1950  
from Sjöassurandörernes Centralforening.

Lloyd's Register of Shipping,  
Tollbugt. 27,  
Oslo.

S/S "BALI".

In connection with a damage to a parcel of electric material the following information was given regarding the cause:

"Water was to be filled on the fresh water tank, but instead of the water entering the tank, it ran into the cargo hold. It appeared that there was a hole corroded in the tank airpipe. The vessel was classed in May 1950 and then part of the pipe was renewed".


Reclassified  
1.46.

We shall be glad to be informed what recommendations were made regarding the airpipe in May 1950 and whether the recommendations were carried out and controlled.

Yours faithfully

SJÖASSURANDÖRERNES CENTRALFORENING

Hans Chr. Bugge (sgd).



© 2020

Lloyd's Register  
Foundation

003495-003502-0103