

9 JAN 1958

Received from Chief Ship Surveyor.....

S NAME "PRECILA" REPORT Smk. No. 794

anding Conditions of Class: Subject to indented side shell plating, bulwark plating etc. (s.s.a) being dealt with as necessary and to the sternframe (E.W. & reinforced 9,54) being specially examined and to port hawse pipe being permanently repaired, next drydocking, also to 45 fathoms of anchor cable being renewed at the earliest opportunity.

ement of Certificate ~~AS before or None~~ ACTION is DEFERRED for completion of S.S. by 4,58.

ys due: SPECIAL SURVEY (D) due 4,57 - commenced Nag. 7,57  
Postponement until 4,58 previously approved.

e of Present Survey: (Afloat ~~and in dry dock~~)

Temporary and deferred repairs to shell plate on account of wear and tear.

al Features:

terim Certificate in order (Yes ~~No~~ ~~None~~)

outstanding ~~(if any for S.S.)~~

FOR PORTION OF SURVEY HELD:- Nag. Rpt.No.728.

to be completed by: 4,58.

endation:

SUBJECT as above, and to wasted shell plate H.16 in way of No.1 hold (p.s.) (doubled 11,57) being specially examined and dealt with as necessary next drydocking, with Endorsement of Certificate., but further ACTION continue to be DEFERRED for completion of Special Survey by 4,58.

~~RECEIVED~~ Subject

ENDORSEMENT OF CERTIFICATE

Indents in shell plating (p & s) and upper deck stringer etc. (s.s.) abreast No.2 hatchway.

S.S. PART HELD.

Lloyd's Register  
Foundation

003495-003502-0181

9 JAN 1958

IT IS FURTHER SUBMITTED the Owners  
be requested to advise this Office  
what arrangements they are making  
to renew the 45 fathoms of chain cable.

6B 24 12 57  
22 11 58



© 2020

Lloyd's Register  
Foundation