

- 32 Essential Independent Pumps (Identify by position)
- 33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
- 34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
- 35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)
- 38 Independent Air Compressors, Coolers & Safety Devices
- 39 Air Receivers & Safety devices—Main 40 Auxiliary
- 41 Oil Fuel Tanks (Not forming part of hull structure)
- 42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?
- 44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

PROPULSION		ELECTRICAL EQUIPMENT	
PORT	STARBOARD		AUXILIARY EQUIPMENT
a Generators			l Generators & Governors
b Exciters			m Motors
c Air Coolers			n Switchboards & Fittings
d Motors			o Circuit Breakers
e Air Coolers			p Cables
f Control Gear, Cables, etc.			q Insulation Resistance
g Insulation Resistance			r Steering Gear Generators and Motors
h Insulating Oil Test			s Navigation Light Indicators
i Overspeed Governors			
j Magnetic Couplings			
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN	AUXILIARY, DONKEY or PRESS
Superheaters	
Safety Valves	
Mountings, Doors & Fastenings	
Safety Valves Adjusted to { Sat.	
{ Spt.	
Boiler Securing Arrangements	
Main Economisers	Exhaust Gas Heated Economisers
Steam Heated Steam Generators	Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?	Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?	Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main	Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?	Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

S.R.L. : Main engine L.P. cylinder foundation (ss) previously reinforced by fitting fabricated steel plate was specially examined and found to continue efficient. It is submitted that the LP cylinder foundation being specially examined by November, 1958.

at

LEAVE THIS SPACE BLANK

Survey fees £10-0-0
 Damage fee
 Expenses... ..

Date when A/c rendered

DEC 29 1957
 LONDON

© 2020

A/c rendered from
 London, 19/12/57

Lloyds Register
 Foundation