

25 JAN 25 1955

Engineer Surveyor

Received from Chief Engineer Surveyor

"RONA"

REPORT

Syd

No. 27788

Orders of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.

~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS~~


This Survey, due 7,54 now held
partly
~~ated, and the following repairs carried out (due to~~):-


Docking. Screwshaft drawn and examined with sternbush. New fitted.

Fractures in boiler front end plates and knuckles and combustion chamber back plates made good by welding. A number mountings overhauled.

It is submitted the vessel is eligible to remain as classed, with

ion of BS 12,54 as recommended.
S 11,54


21.1.55.





© 2021

Lloyd's Register
Foundation

003334-003540-0064