

Received from Chief Ship Surveyor 13 AUG 1962

SHIP'S NAME "J A L A K A N Y A" REPORT CAL. No. 20762

EA

Outstanding Conditions of Class: SUBJECT to indented shell plate No.4 etc.in 2nd below sheer (p.s.f) and to indented plating in 'E' & 'F' strakes frs. '52-53 (p.s) being examined and dealt with as necessary next drydocking, and to set up keel and bottom shell plating (p & s) being specially examined and dealt with as necessary, also to indented shell plate F.4 (s.s.f) being dealt with by the S.S., and to 15 fms. of chain cable be being supplied at the earliest opportunity.

S.R.L. Appendix. (As before ~~XXXXXXX~~)

Nature of Present Survey: (Afloat and in dry dock ~~XXXXXXXXXXXXXX~~)

Permanent/deferred repairs to damage caused by contact.

Recommendation: SUBJECT as above.

As Now Subject.

S.R.L.APPENDIX (AMENDED).

Indented No.5 shell plate in 2nd below sheer (s.s.f).
Shell plate D.2 (s.s.f) indented.

B.M.

21.4.62

© 2020



Lloyd's Register
Foundation