

Do. of Loop.
Do. of R. Qr.

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Steel SS "EASTERN MERCHANT" Rpt. Yka. No. 2556.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 300 Depth "d" 18.25'

Table No. 3 Description Channels & Bulb angles as approved.

Longitudinal No. 40050.

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 11.13

Sheerstrake as approved.

This vessel appears to have been built in accordance with the _____ and the approved plans, and it is submitted she is eligible to be _____ 100 A.1. (steel) "Shelter Deck with freeboard," as _____ ended. The Summer freeboard of 10'-1 1/2" from centre of disc of statutory deck line at Shelter deck, now marked on the _____ sides, to be inserted in the classification certificate, and _____ ed in the Register Book, and further, the remaining freeboards, _____ on the accompanying verification form to be inserted in the _____ cate of classification.

2 Dks (steel) & Shelter Dk. (steel)
Cell DB 386' 1401 t. Turn on the banks. 18' 272 t. FPT. 885 APT. 355
FK. 4 BH to Shelter Dk. 3 BH to Upper Dk. Gen. AYC.P.

included the thickness of steel at fore end, of H strake amidships, is as approved but the Surveyor should be requested to state if this is not, I also state whether oil fuel is carried in double bottom tanks or comp. They should also state the Water Ballast capacities for the various tanks.

003556-003566-0016



2020
AEB
27-2-20

Mr. Manley
20/1/16

BI
" Spac
BEAMS, U
F
" Spac
BEAMS, S

