

4 E
18 MAR 1949

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME "ATLANTIC QUEEN" REPORT P.Sd. No. 4042

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

~~REPAIRS TO ENGINES AND FOLLERS DUE TO DAMAGE THROUGH~~

Due to severe weather conditions the vessel's propeller fouled s.s. "SINGKEP" anchor chain. Propeller examined by a diver and no damage found. The Surveyor recommends the propeller and fastenings be specially examined at the next dry docking.

IT IS SUBMITTED ~~action be deferred pending dry docking.~~

the class be made subject as recommended



© 2021

Lloyd's Register
Foundation

17. 3. 49.

003567-003571-0131