

111 APR 1960

REPORT OF SURVEY ON REFRIGERATED CARGO INSTALLATION BEFORE LOADING

Total capacity of refrigerated cargo space 20,620 cu.ft. Total No. of independently refrigerated chambers 6
Last Report No. 15120 Port TRI.
(To be filled in at Head Office)

Have the chambers specified below, with their air cooler spaces and air ducts (where fitted), been examined in an empty state and found clean and free from which would adversely affect the cargo to be loaded; the air cooler fans and motors (where fitted) been examined under working conditions and found or placed in good order; the brine or other refrigerant pipe grids, cooler coils and connections been examined and found free from leakage; the thermometers with their connections and fastenings, the fixed cargo battens on the vertical surfaces, the cargo gratings or dunnage battens provided for the floors or decks as required to suit the class of cargo been examined and found or placed in good order; the insulation linings and insulation been examined and found free from damage; the scuppers and bilge suction draining insulated spaces been examined and found or placed in good working order, the liquid seals primed, and the refrigerating plant been examined under working conditions? Yes

[illegible]

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done **Complete...**

RECOMMEND THIS INSTALLATION REMAIN AS CLASSED without fresh record.

Surveyor to Lloyd's Register of Shipping

It is submitted that the
vessel's REFRIGERATING IN-
STALLATION is eligible to
remain as classed.

Sub

27 APR 1960



© 2020

Lloyd's Register
Foundation