

med, examined and re-coated and found in good condition.
 700. Balda. Below deck bulkheads and DR to the deck bulkheads,
 Built 1925/10.

VESSEL'S NAME LEME 4 LOWLANDER. REPORT No. _____

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in hundredths of an inch.

KEY.	AMIDSHIP.					FORWARD.				AFT.				REMARKS.		
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.			Diminution if any.	
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.		Port.	Std.
DECK	O	81	76	76	5	5	42	PEAK SIDES			41	P.	42	S		
	N	69	67	67	2	2										
WALKE	M	75	75	75	-	-	50	55	55	-	-	50	55	55	-	-
LOW	L	75	75	75	-	-	50	55	55	-	-	50	48	50	2	-
	K	75	70	67	5	7	50	48	48	2	2	50	55	50	-	-
	J	69	59	63	10	6	50	50	48	-	2	50	42	44	8	6
	H	69	67	67	2	2	50	44	48	6	2	50	46	44	4	6
	G	69	67	63	2	6	50	44	48	6	2	50	50	48	-	2
	F	75	67	67	8	8	50	55	51	-	-	50	60	55	-	-
	E	75					50	55	55			50	75	75	-	-
	D	75					50	-	-			50				
	C	75					50	59	59			50				
	B	75					50	67	71			50				
	A	75					50					50				
HEEL.		106					75					75				

✓ Maintained to coll. - bhd.

RM.
14-9-48.

Drillings at ends to be made in the vicinity of the peak bulkheads.

© 2020
Lloyd's Register
Foundation

003599-003604-0024

good good

efficient? yes
Have Ventilators and their Coamings been examined

Stringers, Clamps & Shelves ditto

eda
d,
w
hila
Items -
ngi
Copper
(s
W
Boats
Masts
Condi
(s
Sails
Equip
Anch
Chain
Cable
"
"
Haw