

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book Survey held at Date, First Survey Last Survey

Supp 88917 on the Wood, Iron or Steel "LUCRINO" (No. of Visits)

Tonnage: Built at Sunderland By whom Sunderland S.B. Co Ltd When 1917 - 7

SS 5616 Owners A Lawo Owners' Address

ER DK 4277 Managers Port belonging to Naples

Keel on or in Dry Dock? Name of Dock Destined Voyage

Depth of Water at Bow DBa feet; uE&B feet; f feet Particulars of Classification

Capacity tons. FPT tons; APT tons; MT feet tons. Only alterations in the existing records of tanks should be inserted.

All alterations in the existing records should be underlined. Report, No. 96554 Port Luc

CHARACTER: for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of N.E., if any).

Surveys when held, must be reported in detail and serially in the terms of the Rules and items remaining to be reported should be summarised.

cases where the Surveyor has not made a special damage report he is required to state whether he has made his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
and Faired or Repaired								
Repaired in place								

CONDITION OF THE		
Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Feet.)
Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Cement or Asphalt	Oil Bunkers	Boats
Rudder	Scuppers	Masts, Yards, &c.
Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Windlass	Hatches	Equipment letter
Have pumps been examined and found efficient?	Planking	Anchors, No. of
Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Have Watertight Doors been examined and found efficient?	Treenails	length mean diam. (on board)
Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
	" " at other places	Standing and Running Rigging
	Stringers, Clamps & Shelves	Sails
	Salting (State if examined.)	

Observations, Opinion as to Class, Recommendation, &c. :-

Clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon the survey, thus, for example: "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	£	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute 8 FRI. 14 APR 1939 Withdraw Class & ... General Committee Thursday 20th April 1939 Lloyd's Register Classing Committee's decision confirmed

Is Certificate required? If so, to be sent to