

Freeboard, Table C.....  
Correction for Length, if required (Para. 12, 13, and 14) .....


3.3 1/4 274

Correction for fall in Sheer (if any).....

FREEBOARD REPORT on the S.S. "Aberdeen".

It is submitted the Surveyor be informed that it is concluded that 5 webs are fitted in No. 4 hatchway as indicated on the approved deck plans, instead of 4 as stated in his report, and he should confirm this. He should also be informed that the freeboards have been computed on the assumption that ceiling is fitted over the entire double bottom, and not under hatches lower bilges only as indicated on approved midship section. (Surveyors report states ceiling fitted)

GKM



© 2020

21.6.17.

Lloyd's Register  
Foundation

003599-003604-0291

† If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.  
+ In vessels obtaining an allowance for deck erections under Para. 11 where the sheer drops abaft amidship beam, the sheer to be taken from the level of the top of the amidship beam.

† State dimensions of freeing port area on back of this form.

¶ The Surveyor should state whether the fall in sheer as reported is measured relatively to the straight line of keel or to the water line. If measured relatively to water line the vessel's draft at time of measurement, both forward and aft, should be reported.