

26 NOV. 1962

Ship's Name ~~SS~~/MS "ANNIE JOHNSON" of Stockholm Gross tons

Is there a rpt. 8? Port Stockholm Rpt. No. 13937.

No. of visits First date Last date

Interim Cert. issued & copy herewith? Damage rpt. issued & copy herewith? Last rpt. (H.Q. only)

Date of completing rpt. Surveyed at, if different from Port above

Is a rpt. 9A attached? Yes MN Nature of survey GENERAL EXAMINATION.

Survey fees Damage fee Expenses

S.A. fee

DOCKING

Propeller Sea connections Oil gland

Fastenings Wear down of stern bush

Has screw/tube shaft been drawn? Date of examn.

Has shaft been changed? Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner? Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of each boiler.)

AUXILIARY, DONKEY OR PRESS (State if oil fired—OF or exhaust gas—EG) MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves { Sat adjusted to { Spt

Boiler securing arrangements

Main economisers

Exhaust gas heated economisers

Steam heated steam generators

Steam generator safety valves adjusted to

Forced circulating pumps

Funnel

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Were oil burning system & remote controls examined in accordance with rules ?


I recommend that the machinery of this ship remain as classed with/without fresh record of

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

FRIDAY - 7 DEC 1962

Minute



Lloyd's Register Foundation

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

003605-003610-0284

003605-003610-0284

State Port Start  
be omitted from forward.  
described fully under "defects and repairs".  
Identify by position  
Where repairs have been effected or it is

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a	Generators	l	Generators & governors Good
b	Exciters		
c	Air coolers	m	Motors
d	Motors		
e	Air coolers	n	Switchboards & fittings
f	Control gear cables, etc.	o	Circuit breakers
g	Insulation resistance	p	Cables
h	Insulating oil test	q	Insulation resistance Good
i	Overspeed governors	r	Steering gear generators & motors Good
j	Magnetic couplings	s	Navigation light indicators
k	Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



Surv

5020

Nov

and

of

that

my

This Certif  
" While the C  
understood th  
any inaccurac  
the Society, or  
er Officers or A

Cert. C1.)—1m,

