

Rpt. 8

Port Oslo

No. 9211

Date of writing Report 28/1/61

When handed in at Local Office 28/1/61

Received London

31. JAN. 1961

Survey held at Kristiansand

No. of Visits one

First Date 27/1/1961

Last Date 27/1 1961

# REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B. 74250

on the Iron or Steel <sup>SS</sup> ~~MSX~~ "OAKLEY"

Tons gross 8100

Built at Wallsend

By Whom Swan Hunter & Wigham & Carter Co. Ltd.,

When Year 1941 Month 8

Owners Harald A. Møller A/S

Owner's address (If not already in R.B.)

Managers Torvald Klaveness

Port of Registry

Surveyed Afloat or in Drydock Afloat

Name of Dock Kristiansand

Date of last examn. in Drydock -

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 60867

Port Bff

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
+ 100 A1 Oil Tanker	+ LMC. 6/58
S.S. Dr. 6/58	MBS. 6/58
D.S. 5/59	TS (CL) 6/58
	Sps. 5/58

Give dates and references to any letters relating to this Report

In damage cases where the Surveyor has not made a special damage report he should state whether he offered his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR Towing to Hamburg for breaking up.

Now Done:- Vessel examined afloat whilst laid up.

All hatch covers, companionways, door openings, ventilators, superstructure end bulkheads and all skylights found efficiently closed.

The sea valves in motor room and pump room closed. During the voyage no steam or electric power will be available, but the anchors can be dropped but not recovered.

In view of the examination now made it is considered that the vessel is in a satisfactory condition to be towed to Hamburg as and unclassed hulk.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed				I				
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship? No

Is Classification Certificate required? If so, to be sent to No

If so, is the Report sent now, or when will it be sent?

Has Interim Certificate been issued? Yes, copy attached.

### GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This ship so far as now seen is in my opinion in a satisfactory condition for towing to Hamburg as an unclassed hulk.

*David T. Grant*  
Surveyor to Lloyd's Register of Shipping  
David T. Grant.


Date of Committee

THURSDAY 23 FEB 1961

Minute

Deferred - await further information

Noted for Header



© 2020

Lloyd's Register Foundation

003625-003630-0035

**TABLE 1**

PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR SURVEY

Items	Now Examined YES NO or NONE	Tanks	Now Examined Internally	Now Tested
Shell plating, sternframe and rudder cleaned, examined and recoated in drydock		F.P. Tank		
Rudder lifted		A.P. "		
Weather Decks, Superstructures and Casings		D.B. Tanks (indicate Oil Fuel and Cofferdams)		
Hatchways, Covers, closing and securing appliances				
Ventilator coamings, skylights, companionways and closing appliances		Fresh Water Tanks		
Holds		Deep Tanks		
'Tween Decks		Oil Fuel Bunkers and Settling Tanks		
Fore Peak Spaces		Side Tanks		
After " "		Wing Tanks		
Engine Space		Other Tanks		
Boiler "		Cargo Tanks (Tankers)		
Under Engines and Boilers				
Tunnel and Well		Cofferdams		
Coal Bunkers		Pump Rooms		
Chain Locker				
Other Spaces				
		Have Tanks now Examined been Cleaned as Necessary?		
		Have Strains in Cargo Tanks (of Tankers) been removed?		
		Have Tanks been Retested as necessary after completion of any Repairs?		

SURVEY CONTINUED TO FORWARD.

Have the spaces now surveyed been cleared and cleaned as necessary? \_\_\_\_\_

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and repaired as required by the Rules? \_\_\_\_\_

Have the bilges been cleaned out and examined? \_\_\_\_\_ Has cement in bottom been examined? \_\_\_\_\_

Has steelwork had rust removed and afterwards been recoated as necessary? \_\_\_\_\_

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? \_\_\_\_\_

Has a Load Line Survey been held? \_\_\_\_\_ If so, state which \_\_\_\_\_

Have the shell and deck plating been drilled as per Rule? \_\_\_\_\_ If so, Report 8(Dr) to be attached \_\_\_\_\_

Have any alterations to the approved scantlings and arrangements now been effected? \_\_\_\_\_ If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

**TABLE 2**

The present condition of the following parts in so far as examined is to be reported:—

Shell plating	Ceiling and Cargo Battens	Sluice Valves examined and found
" " in way of side scuttles	Cement or Asphalt	Air and Sounding Pipes
Rudder and Sternframe	Cargo and other Hatchways	Doubling Plates under Sounding Pipes
Decks	Hatches and closing appliances	Masts and Rigging examined and found
Superstructures and their closing appliances	Ventilators, their coamings and closing appliances	Condition, how ascertained (State if wedges removed)
Coamings and Casings	Companionways and Skylights	Chain Locker
Beams and Fastenings	Shell Openings	<b>EQUIPMENT</b>
Frames	Ash Shoots	Equipment Letter
Reverse Frames	Overboard Discharges and Scuppers	Anchors, No. of Condition
Longitudinals	Freeing ports	Cables (State if now ranged and examined)
Transverses	Steering Gear (Main and Auxiliary)	" length mean diam. (on board)
Floors	examined and found	" Rule Length Size
Keelsons	Windlass examined and found	Hawsers and Warps
Stringers	Pumps " " "	State if any Anchors or Chain Cable have
Inner Bottom Plating	W.T. Doors " " "	now been supplied or retested, if so
Bulkheads and Tunnel		complete Report 8(Eq) and attach.

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? \_\_\_\_\_ See Below \_\_\_\_\_

REMARKS, REPAIRS, Etc. (Contd.) \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Survey Fee \_\_\_\_\_ Kr. 200.- Second Surveyor's Fee (if any) \_\_\_\_\_

Special Damage or Repair Fee (if any) \_\_\_\_\_ Date when A/c. Rendered \_\_\_\_\_

Travelling Expenses (if chargeable) \_\_\_\_\_ Kr. 200.-

