

10 MAY 1961

NAME "NATICINA"

REPORT SNG

No. 14677

EA

ding Conditions of Class:

SUBJECT to set up keel plating in way of Nos. 1 & 4 tanks being specially examined and dealt with as necessary by the S.S., also to upper deck plating 1st strake inboard of stringer (p.s.) between frs. 65-87 and 118-152 (thin) being specially examined and dealt with as necessary next drydocking.

Appendix. ~~(As before)~~ None)of Present Survey: ~~(As before)~~ in dry dock)


Docking:- Deferred repairs to grounding damage.

ndation:

SUBMITTED record of DS 3,61 be assigned, subject as above and to Nos. 6 & 7 keel plates from fwd. and structure in way being specially examined and dealt with as necessary before the ship is put into service.

DS 3,61 Subject.

NOTE:- It would appear from this report that the ship is being taken out of service for lay-up.

ENGINEER SURVEYORS TO NOTE.

2020
Lloyd's Register
Foundation