

Surveyors.....

Received from Chief Surveyors.....

Rpt 9.

ME

Regents Jaquar

REPORT

n. yk

No. 52914

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Temporary repair. When due

hated

Subject to two bolts fitted in way of Donkey
Boiler Space (SS) being replaced with rivets
next hydrocking.

See letter dated 28/1/54

The Surveyors should be requested to advise
in which part of the structure the above
bolts have been fitted



Lloyd's Register
Foundation

RSD
6-1-54

003706-003711-0214

being fit to carry Petroleum in bulk.

over, and
und true