

COPY

Ship's name

"MULBERRY HILL"

Port

Msl.

No.

13863

3.3.64.

Last survey date

GB

Class is subject to

riveting of shell plates in
'D' & 'E' strakes between frames 105/115 in way of No.2
hold (p.s) being specially examined and dealt with
as necessary next drydocking.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

Examination afloat after grounding.

Recommendation

SUBJECT as above, and to starboard
anchor chain cable being specially examined
for possible damage next drydocking
but further ACTION be DEFERRED for
examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX

Lower stem bar set over to port.

Bottom shell plating slightly corrugated.

Shell plates A.5 & B.1 (p.s.a) & 4.4 (p.s.f) and

stern wrapper plate indented.

F.9, E.9 & 10 (s.s. amid) slightly wavy.

© 2020

Lloyd's Register
Foundation