

Received from Chief Ship Surveyor 5 DEC 1960

AME

"NEVERITA"

REPORT

Ams.

No. 23801

ing Conditions of Class: SUBJECT to shell plating butt 'D' strake (fractured and doubled) in way No.8 starboard wing tank and to bottom shell plating in No.4 wing tank (p & s) (fractured and doubled) being specially examined and dealt with as necessary, also to bottom shell plating (fractured and doubled) in way of No.9 wing tank (p & s) being dealt with as necessary, next drydocking.

Appendix. (As before ~~as None~~ ~~xxxxxxx~~)

of Present Survey: (Afloat and in dry dock)

Docking: Subject item repairs:
Drilling of shell and deck plating for pre Special Survey
drilling as per Circular No.2106.

Adation:


SUBMITTED record of 'DS 9,60' be assigned as recommended, but without special conditions.

DS 9,60 Without.

IN S.R.L. APPENDIX.

Bottom shell plates B.5,6,8,10,12 & 14 (s.s.)
B.9 & 15 (p.s.) (all from aft), A 3 (p.s.f)
and keel indented.

SHIP RESEARCH DEPT.
TO NEXT MASTER COMMITTEE



© 2021

James
30/11/60

Lloyd's Register
Foundation

003838-003845-0286