

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address: Inland: Committee, London, Telex  
Overseas: Committee, London E.C.3  
Your Ref: Technical/AH/2018

Telephone: ROYal 9166  
Telex No.: 24305  
18th November, 1963

C  
RLT/BDF

Dear Sirs,

"CLAN MACAULAY"

Referring to your letters dated 30th October and 12th November a report has now been received from the Society's Surveyor at Takoradi. Whilst the ship was at that Port during October the Surveyor reported that the plating of the forward centre boiler in way of the main check valve opening, was severely corroded and pitted, and it has been recommended that this item be specially examined and dealt with as necessary on completion of the present voyage or by December 1963.

The Surveyor also reported that one length of feed piping attached to the main feed check of the forward port boiler was found leaking. The pipe was generally pitted and it has been recommended that it be renewed on completion of the present voyage and before the end of December 1963.

Yours faithfully,

Deputy Clerk to the  
Classification Committee

The Houston Line Ltd.,  
4 St. Mary Axe,  
LONDON, E.C.3.



© 2020

Lloyd's Register  
Foundation

003958-003963-0142