

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 23rd OCT 1941 When handed in at Local Office 19 Port of GLASGOW.

No. in Survey held at GLASGOW. Date, First Survey 7.10.41 Last Survey 12.10.1941

Reg. Book. on the Wood, Iron or Steel S.S. 'EMPIRE BAFFIN' (No. of Visits 1)

36311 TONNAGE: Built at PORT-GLASGOW. By whom LITHGOW'S. LD. When 1941
GROSS 4818 Owners MINISTRY OF WAR TRANSPORT. Owners' Address
UNDER DK. Managers J. ROBINSON & SONS. Port belonging to GREENOCK.
NET

Surveyed Afloat or in Dry Dock? AFLOAT. Name of Dock PRINCES DOCK. Destined Voyage
Cell DBor DBa feet; uE&B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.
N.B.—All alterations in the existing records should be underlined.

Last Report, No. Port

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR TEMPORARY STRENGTHENING FOR NAVIGATION IN ICE.

Visited vessel at the request of Ministry of War Transport, (Sea Transport dept.) to arrange temporary stiffening of shell plating forward for navigation in ice.
It was arranged to fit the stiffening to shell plating in way of fore peak and forward 19 frame spaces of No. 1 hold, extending from upper line of ridge to about 1'-0" above load line. The stiffening to consist of timber fitted between frames, wedged from fore & aft bulk angles fitted on face of frames. (4 each side of vessel in way of No. 1 hold)

Owing to late delivery of the material required, the stiffening was only partially fitted during the night previous to the vessel sailing, work being suspended at 8 am to permit loading of No. 1 hold, and commenced in way of fore peak on the morning vessel was due to sail

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Fett.)
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Caulking of Decks	Cement or Asphalt	Oil Bunkers	Boats
Coamings	Rudder	Scuppers	Masts, Yards, &c.
Beams & Fastenings	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Outside Plating	Windlass	Hatches	Equipment letter
" " in way of sidelights	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board)
Longitudinals	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Transverses	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Floors	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Keelsons		" " at other places	Standing and Running Rigging
Stringers		Stringers, Clamps & Shelves	Sails
Inner Bottom Plating		Salting (State if examined.)	
Have the Tanks been examined internally?			
Have the Tanks been tested?			

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

For the information of the committee.

Survey Fee (per Section 20)	£ 5 : 5 : 0	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	19
Travelling Expenses (if chargeable)	£	Received by me,
Second Surveyor's Fee (if any)	£	19

Committee's Minute GLASGOW 28 OCT 1941

Character Assigned As now

Surveyor to Lloyd's Register of Shipping.

© 2020 Lloyd's Register Foundation

004019-004028-0110