

under special survey, tested under full working conditions and found satisfactory. The material and workmanship is good. All

4 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME *Empire Baffin*

Rpt. *Gl.* No. *64470*


\*Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

*This vessel's machinery appears to have been built in accordance with the Rules, approved plans & M.O.S. specification. The Boilers have been built under the special survey of the British Corporation, but fitted on board under the supervision of the Society's Surveyors. It is submitted that it is eligible to be classed*

*LMC \* 10.41  
FD. S(CL)*



*440*  
Lloyd's Register  
Foundation  
*5/28/41*

004019-004028-0112