

SHIP'S NAME "FIROZA"

REPORT Krh

No. 3078

Outstanding Conditions of Class:

SUBJECT to sternframe (E.W. & part renewed 5,57) being specially examined and dealt with next drydocking, also to shell plates B.15, D.11, G.15 and J.15 (s.s) to boundary of after E.R. bulkhead (p & s), to No.4 hold after bulkhead, to tunnel riveting and starboard forward bulwarks etc., being dealt with as necessary by 10. 59.

R.L. Appendix. (~~XXXXXXXXXXXX~~ None)Structure of Present Survey: (Afloat and ~~XXXXXXXXXXXX~~ in dry dock)Examination of deferred items as above.Recommendation:

SUBJECT to sternframe (E.W. & part renewed 5.57) being specially examined next drydocking, also to shell plates B.15 D.11, G.15 and J.15 (s.s) to boundary of after engine room bulkhead (p & s) to No.4 hold after bulkhead, tunnel riveting and starboard forward bulwarks etc., being dealt with during the ship's present stay at Karachi.

Now

SUBJECT:  
Amended:

RE.

The Owners have not yet reached a decision regarding the future of the ship.



© 2020

Lloyd's Register  
Foundation

004107-004115-0097