

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Steel SS "CLAN MACIVER"*Report *Gr. E.*

No. 17838.

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/02.)

Nature of Survey _____

When due _____

✱ 100 A.1. (steel).


2 Dks (steel).

Cell DB 329' 949t.

DTa 30' 774t.

FPT 122t. APT 19t.

FK. Intermediate tween deck bulkhead in after hold dispensed with. GBH
to upper Dk. 1BH to 2nd dk. only. Conn. Lloyd's AICP P49, B 113, F 38'



It is concluded the thickness of tops of forecath side plating & the strengthening of sheenfraks at ends of bridge, are all as approved, but the Surveyors should be requested to state if this is so.

© 2020
Lloyd's Register
Foundation
004206 004212-0150