

Rpt. 8.

(Received at London Office.)

No. 7923

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 8th February 1949.

When handed in at Local Office 8. 2. 1949.

Port of

No. in
Reg. Book.

Survey held at DARTMOUTH.

Date, First Survey 31. 1. 49.

Last Survey 5th February, 19 49.

(No. of Visits Four)

95502

on the ~~Woolwich~~ Steel

"POLURRIAN"

TONNAGE :-

GROSS 328

UNDER DK. 233

NET 149

Built at Dartmouth

By whom Philip & Son Ltd.,

When 1948

MONTH 7

Owners Coastal Freighters Ltd.,

Owners' Address

(If not already recorded in Appendix to Register Book).

Managers

Port belonging to Dartmouth

Surveyed Afloat or in Dry Dock? Afloat.

Name of Dock Dartmouth.

Destined Voyage

Cell DBor DBa feet; uE & B feet; f feet
total capacity tons. FPT tons; APT tons; MT feet tons.Particulars of Classification (which must be inserted
precisely as in Register Book & Supplements)CHARACTER.
* for Special Survey
Date of last Survey and of
Periodical Surveys.Machinery and Boiler
Surveys
(Including date of N.B., if any).

+ 100 A.1.

+ L.M.C. 7,48

Oil Engine.

O.G.

J. J. E.

Society's Freeboard (if assigned) as
painted on Ship and now verified ft. ins.In damage cases where the Surveyor has not made a special damage report he is required to state whether he
offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR ALTERATIONS TO STEERING GEAR.

The steering gear has now been altered in accordance with the approved plan and Secretary's letter of
28. 1. 49., tried at sea and found satisfactory in every respect.

SUMMARY OF DAMAGE REPAIRS :-

Renewed ...
Removed and Faird or Repaired
Faird or Repaired in place ...

Shell Plates.

Frames.

R. Frames.

Floors and
Bracket Floors

Beams.

Inner Bottom
Plates.

Dk. Plates.

Other Items :-

PRESENT CONDITION OF THE

Decks
Caulking of Decks
Coamings
Beams & Fastenings
Outside Plating
" " in way of sidelights
Frames
Reverse Frames
Longitudinals
Transverses
Floors
Keelsons
Stringers
Inner Bottom Plating
Have the Tanks been examined internally?
Have the Tanks been tested?Bulkheads
Ceiling
Cement or Asphalt
Rudder
Steering gear and its connections
Windlass
Have pumps been examined and found effi-
cient?
Have Sluice Valves been examined and found
efficient?
Have Watertight Doors been examined and found
efficient?
Have Ventilators and their Coamings been
examined and found efficient?
Air and Sounding Pipes
Doubling Plates under Sounding PipesEngine Room Skylights
Coal Bunkers, Openings, Covers, &c.
Oil Bunkers
Scuppers
Cargo Hatchways
Hatches
Planking
Caulking
Treenails
Breasthooks & Stemson
Transoms, Pointers & Crutches
Timbers of Frame at openings
" " at other places
Stringers, Clamps & Shelves
Salting
State if examined.Copper, or Y.M.
(State if on Felt.)
When fitted, Month Year
Boats
Masts, Yards, &c.
Condition, how ascertained
(State if wedges removed.)
Equipment letter
Anechors, No. of
Cables (State if now ranged)
" length mean diam.
(on board.)
" Rule length size
Chain Locker
Hawsers & Warps
Standing and Running Rigging
Sails

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon
this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of
survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."This vessel, as far as now seen, is in an efficient condition and eligible in my opinion
to remain as classed without fresh record of survey.Survey Fee (per Section 29) £ : : Fees applied for,
Special Damage or Repair Fee (if any) £ 10 : 10 : 0 19
(per Sec. 29)
Travelling Expenses (if chargeable) £ : : Received by me,
Second Surveyor's Fee (if any) £ : : 19

Committee's Minute.

Character Assigned.

As new

subject (sm) not

Surveyor to Lloyd's Register of Shipping.

© 2021

Lloyd's Register
Foundation

004222-004224-0031

Also been held on the Machinery of the Ship?
If so, the Report sent now, or when will it be sent?10m. 4. 4. - Transfer Ink.
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

Is Certificate required? If so, to be sent to