

PT

COPY

MAY 1965

Ship's name

"APJ AMBAR"

Port

COCHIN No. 176

Class is subject toLast survey date 5.4.65

NONE

ACTION is DEFERRED for examination in drydock
after grounding.

S.R.L. Appendix (as before on ~~xxxxxxx~~)Nature of present survey (afloat and in drydock) ~~xxxxxxxxxxxxxxxx~~

Equipment:- Loss of bower anchor and 15 fathoms of chain cable;
4 shackle pins found slack;
60 fathoms of chain cable disconnected.

Recommendation

and 60 fms of chain cable being repaired on ship's arrival at Calcutta
being reconnected

SUBJECT TO bower anchor and 15 fathoms of
chain cable being supplied at the earliest
opportunity and 4 defective shackle pins
being repaired on ship's arrival at Calcutta
from present voyage, but ACTION Be DEFERRED
for a short time for equipment and for
examination in drydock after grounding.

SUBJECT

IN S.R.L.

Drydocking (grounding)

IN S.R.L. APPENDIX

Indented shell plating in way of
Oil fuel bunker (p.s)
Shell plate (p.s. amids) pitted.

DA. 11/5/65
U/S CAL 7.5 EQUIP
COND