

- 2 APR 1965.

Ship's name *APT AMBAR*

Port

*CAL*

No. 1570

Last survey date *22/2/65*

Class is subject to -

Exhaust turbine not being used until specially examined and seen under working conditions.

*CSM completed.*

SRL Item: The Surveyor reports no repair facilities available to effect repairs to the turbine, the reduction gearing and hyd. coupling were not examined and the Surveyor recommends the exhaust turbine unit not to be used until repaired and surveyed.

Some electrical circuits found with low insulation resistance. due to the vessel's sailing commitments no repairs were effected and the Surveyor recommends defective electrical circuits be repaired by 5/65 (3 max limit)

It was stated the propeller blades were damaged due to contact with mooring buoy. all blades dressed as far as practicable and the Surveyor recommends the propeller and fastenings be specially examined at next dry docking

It is submitted that this vessel is eligible for THE RECORD. *CSM 2/65*

Subject as above as now amended and subject as recommended.

CERTIFICATE WRITTEN



© 2020 *2/2/65*

Lloyd's Register  
Foundation