

1E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME "MARACAY" Rpt. Belfast No. 10641.

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Engine Triple Expansion.

If Boilers fitted with forced draught *yes.*

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of } *yes.*
approved type

This vessel's machinery appears to have been built in accordance
the Rules and the approved plans, and it is submitted she is
able to be classed + L.M.C. 6.31. O.G.

Fitted trial fuel 6.31 2Habs 150° J.
The combined screw & tube shaft appears to be fitted
two liners it is concluded that the designation
is a clerical error.

CM.

23/6/31.



© 2021

Lloyd's Register
Foundation

004564-004572-0221

004564-004572-0222 1/3