

MC5,55
56

6

The class is subject to a defective stay tube in the starboard box ~~the~~ the stbd boiler being renewed at the earliest opportunity.

18 JUN 1957 4E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

PORTELET

REPORT Hul

No. 63087

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

document to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points set out in the endorsement. - Extract from Sub-Committee's Report, 24/5/52.

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

MBS due 6.57, partly held 5.57, now complete.

IT IS SUBMITTED that this vessel is eligible for the record MBS 5.57 subject as above.

Mt
14.6.57.



© 2021

Lloyd's Register
Foundation

004603-004611-0073