

Rpt. 9B

REPORT OF MACHINERY SURVEYS AND REPAIRS  
FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London

Ship's Name <sup>Xy</sup> MS TOMAR

Port New York

Processing Number: LR 536414

Gross tons 6410

Rpt. No. 65988

Port of Registry Tonsberg

Date of build

Is there a rpt. 8?

No. of visits

First date

Last date

Interim Cert. issued & copy herewith?

Damage rpt. issued & copy herewith?

Last rpt. (H. Q. only)

Date of completing rpt.

Surveyed at, if different from Port above

Is a rpt. 9A attached? Yes

MN

Nature of survey

ABS

Survey fees

Damage fee

Expenses

S.A. fee

BOILERS OPENED UP AND EXAMINED. (Identify by position and state condition and latest date of internal examination of each boiler, economiser or steam generator)

AUXILIARY, DONKEY or PRESS

(State if oil fired—OF or exhaust gas—EG)

MAIN

Air heaters

Superheaters

Safety valves

Mountings, doors and fastenings

Safety valves adjusted to { Sat Spt

Boiler securing arrangements

Main economisers

Steam heated steam generators

Fired boiler forced circulating pumps

Have saturated steam pipes in cylindrical boiler smoke boxes been examined as required by the Rules?

Auxiliary Boiler (OF/EG): 100 psi

Exhaust gas heated economisers and their safety valves

Steam generator or E.G.E. safety valves adjusted to

Funnel Were oil burning system & remote controls examined in accordance with Rules?

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply, namely, International voyages/voyages within the limits

(The above declaration applies only to sea-going cargo ships of 500 tons gross and above registered in the U.K.)

I recommend that the machinery of this ship remain as classed with/without fresh record of

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

Minute

See Rpt-9A NEW YORK JUN 6 1967

J.A.C. Graham

J. A. C. Graham

Surveyor to Lloyd's Register of Shipping

ALSO FOR


SRL FOR

TRO NOTED BY CESR SRL

POSTING

HEADER

CERT



© 2020

Lloyd's Register Foundation

004684-004692-020

are to be cancelled; this need not be done when the machinery is on a continuous survey basis. When any part has been hydraulically tested the pressure should be stated. Engine parts when referred to by numbers should be counted from forward.

that date a distinguishing mark (thus) should be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where re-examination or repairs should be made before

EXAMINATION AND TESTING OF STEAM PIPES (state material and test pressure and, if selected lengths, identify by position)

MAIN

AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler  
smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a	Generators	l	Generators & governors
b	Exciters		
c	Air coolers	m	Motors
d	Motors		
e	Air coolers	n	Switchboards & fittings
f	Control gear cables, etc.	o	Circuit breakers
g	Insulation resistance	p	Cables
h	Insulating oil test	q	Insulation resistance
i	Overspeed governors	r	Steering gear generators & motors
j	Magnetic couplings	s	Navigation light indicators
k	Air gap		
t	Spare gear		

u PASSENGER SHIPS Have the emergency source of power and its associated circuits and, where fitted,  
the temporary source of power and its automatic arrangements been tested?

CARGO SHIPS Have the emergency source of power and its associated circuits been tested?

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Auxiliary Boiler Survey now complete. See New York Report dated May 1, 1967  
for commencement of the survey.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2020

Register  
Foundation