

COPY

Ship's name *SALAMANNA*Port *RIO*No. *9602*Class is subject to *—*Last survey date *25 5 64*

- (1) Item Condenser water box being examined at the earliest opportunity
- (2) Stokers furnace of port boiler being specially examined and checked by 2/64 (1933 record 9/63 being withheld)

1933 due 6/63, commenced 9/63

SAL Item examined, calibrations taken. No previous furnace calibrations on board. The Owners requested repairs be deferred until such time as a decision reached regarding the future of the ship on account of shell damage sustained by port dry.

The Surveyor recommends the ~~outboard~~ port boiler outboard furnace be repaired or renewed by 7/64 (3 mos limit)

It is submitted that the vessel WILL BE eligible for the record when the survey has been completed.

*Subject as above re Item (1)
and as now recorded re Item (2)*



© 2021
Lloyd's Register
Foundation

To Complete 1933 Subject item to be dealt with