

16 OCT 1962

Received from Chief Ship Surveyor.....

NAME "SALAMMANNA" REPORT LA No. 5638a
LA 5638

EA

Standing Conditions of Class:

SUBJECT to set in shell plating etc. (s.s) abreast No.3 hatch being specially examined and dealt with as necessary at Martinique, and to indented shell plate in way of No.4 hold (s.s) and structure in way being specially examined and dealt with as necessary next drydocking.

Appendix. (As before ~~XXXXXX~~)e of Present Survey: ~~XXXXXX~~ in dry dock)

Permanent repairs to shell plating etc. abreast No.3 hatch as above.

Recommendation:

SUBMITTED record of DS 6,62 be assigned as recommended, SUBJECT to indented shell plate in way of No.4 hold (s.s.) and structure in way being specially examined and dealt with as necessary at the next drydocking, without other conditions.

DS 6,62 Subject
without.

IN S.R.L. APPENDIX.

Indents in side shell plating (p & s).
Poop side (p.s) indented.



© 2021

Lloyd's Register
Foundation

DRP
5.10.62