

31 MAY 1966

GB Ship's name "ANGELIC" Port Cochin No. 330Last survey date 26.4.66Class is subject to

set in stern counter plating and upper deck plating in way being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for examination in dry dock after grounding.

S.R.L. Appendix (as before ~~xxxxxxxx~~)Nature of present survey (afloat and ~~xxxxxxxxxxxx~~)

Deferred repairs to damage (cause not stated).

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
ENGINEBOARD	E. REPORTS	PUBS.

Recommendation

SUBJECT as above, and to set in shell plating in 3rd strake below sheer between frames 5/9 from forward bulkhead in No.3 hold (p) being specially examined and dealt with as necessary next drydocking but further ACTION be DEFERRED for examination in dry dock aftergrounding.

SUBJECT

IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX

Indents in shell plating (p & s).

Bottom plating slightly wavy.

OFFICE NOTE:- Bottom plating and inner bottom plating in

No.3 hold stiffened - Rot.11,52.

Crack arresters fitted to upper deck beam 54-155(p&s) -

St.J.3,53.

© 2020

Lloyd's Register
Foundation

31-5-66