

Ship's name

"MANSOOR"

Port Krh

No. 515

Last survey date 14.7.64.

Class is subject to

NONE

ACTION is DEFERRED for examination in dry dock
after grounding.

S.R.L. Appendix (as before of ~~none~~)

Nature of present survey (afloat and in drydock)


Docking: Temporary repairs to grounding damage.
Examination of S.R.L. Appendix items.

Recommendation

SUBMITTED record of 'DS 7,64' be assigned,
subject to set up keel plates Nos.1 & 2
from forward being renewed and to centre
girder in way being specially examined and
dealt with as necessary by 4,65.

DS 7,64. Subject
~~DELETE FROM S.R.L.~~
Drydocking (grounding).
IN S.R.L. APPENDIX.

Indents in shell plate No.2 in 3rd below sheer (s.s.f).
F.7 (ss), F.3, 4 & 5 (ssf), G.5 (p.sf) slightly indented.



Handwritten notes: "15/8-64" and a signature.