

Ship's name "KAVO MATAPAS"

Port

BDX  
NTS

No. 1083

Class is subject to nil

Last survey date 1/2/65  
5/2/65

Bdx Sur reports damage to furnaces of  
Port main blr. No repairs carried out at  
Bdx.

The Rankes Sur reports general examination of  
std blr for voyage to Bto, where repairs  
to port blr will be effected.

The Sur damage report makes mention of  
vessel being examined afloat after grounding & it  
is considered the propeller & forkings  
(grounding) should be specially red at the  
next 1970

The Sur also recommends the port main blr  
be re-examined & repaired as necessary ~~the std~~  
~~blr be examined through~~ the on arrival at  
Bto, where vessel proceeding.

1971 due 7.64 count. 9.64.

1/2 Bto 12.2  
MBS Dam

004918-004926-0178 1/2

© 2020

Lloyd's Register  
Foundation  
(See over)



Ship's name *KAYO MATAPAS*

Port

No.

Class is subject to

Last survey date

*Sheet 2*

*It is submitted that the vessel WILL BE eligible for the record MBS 9.64 when the survey has been completed.*

*subject as now recommended.*

*G. T. A. 5/3/65*

*LLB*

To complete MBS

*Shd bly to examine, S/O  
if both bly to be adjusted under  
Steam, oil burning system & remote  
controls to examine working & subject  
items dealt with.*