

3 SEP 1965

Ship's name "LVA CAPE"

Port

MLT

No. 3400

Last survey date 6.8.65

Class is subject to indented shell plates K.19 & 20 and L.20 etc.

(p.s. from aft) and set in stem and stem plating and to spare propeller pedestal and fastenings being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (as before ~~XXXXXXXX~~)

Nature of present survey (afloat and in drydock)

Docking: Wear and tear repairs.

Equipment: 135 fathoms of chain cable found worn below renewal.

Examination of part S.R.L. and S.R.L. Appendix items.

Recommendation

SUBMITTED record of DS 8.65 be assigned subject as above and to 135 fathoms of chain cable being replaced at the earliest opportunity but ACTION be DEFERRED for a short time for equipment.

DS 8.65 Subject.

IN S.R.L. APPENDIX

Sheerstrake plates Nos.5 & 6 (s.s. from aft) indented.

P.T.O.

© 2020
Lloyd's Register
Foundation

IT IS FURTHER SUBMITTED the Surveyors be advised that the following conditions of class was imposed by the Khorramshahr Surveyors in 6.65:- ' Spare propeller pedestal and fastenings being specially examined and dealt with as necessary next drydocking.

It is concluded that this has now been dealt with but not reported since they were not aware of this condition and since this is not a classification item. *Confirmation is desired*

[Handwritten signature]

XXXXXXXXXX


27/11
2-9-64

work and tear repairs.
Equipment: 155 fathoms of chain cable found worn below
renewal.
Examination of part S.R.I. and S.R.I. Appendix
items.
SUBMITTAL record of US 6.65 to be assigned subject
as above and to 155 fathoms of chain cable being
replaced at the earliest opportunity but
ACTION be taken for a short time for equipment.

US 6.65 subject.

Sheets plates Nos. 5 & 6 (S.S. from aft) indented.

S.R.I.



© 2020

Lloyd's Register
Foundation