

PT

22 MAR 1965

Ship's name

"SAN FERNANDO"

Port

CBO

No.

5805

Last survey date 9.12.65

Class is subject to

set in shell plates H.8 & 9, aJ.8 and K.9 (s.s. from aft) together with framing in way being specially examined and dealt with as necessary next drydocking.

S.R.L. Appendix (~~as before~~)

Nature of present survey (afloat ~~xxxxxx~~)

Damage (fire) in Nos. 1, 2 & 4 holds, no structural damage found. Damage (contact) involving 'H' & 'J' strake plating (p & s) in way of frames 68-73. Temporary repairs effected.

Recommendation

SUBJECT as above, and to shell plates in 'H' & 'J' strakes in way of frames 68 (p.s) and 71-73 (s.s) and upper deck plating in way being permanently repaired next drydocking by 4, 65, and to set in shell plates F.6 & G.7 etc. (p.s.a) being specially examined and dealt with as necessary by the S.S.



© 2025 *S.R.L.*
2/3/65

Lloyd's Register
Foundation