

S. S. SEMIRA  
Repair to thrust block.  
Venice Report No 0266

Fig. No 1






Fig. No 2



© 2021

Lloyd's Register  
Foundation

005311-005317-0010