

19th April, 1960

FALMOUTH

13717, 727, 729 - As recommended.

13726 "SAN SALVADOR" - As recommended. It is concluded that you drew the attention of the Owners' Superintendent to the sternbush wear down which is approaching the practical limit for renewal of the wood.

13728 "SANDALWOOD" - As recommended, except that the notation ABS 3,60 has been assigned.

It is concluded that the auxiliary lubricating oil pump and auxiliary jacket pump in the report refer to the independent main lubricating oil pump and independent main jacket cooling water pump, but your confirmation is desired.



© 2020

Lloyd's Register
Foundation